MANAGEMENT SYSTEM CERTIFICATE

Site certificate No.:
238682CC10-2017-AHSO-ITA-ACCREDIA

Valid:
06 August 2026 – 01 August 2029

Belongs to main certificate number:
238682-2017-AHSO-ITA-ACCREDIA

This is to certify that the centrally implemented management system for

MA Automotive Deutschland GmbH - Werk Treuen

Treuener Hoehe, 1 - D-08233, Treuen, Germany

and the sites as mentioned in the appendix accompanying this certificate

has been found to conform to the Occupational Health and Safety Management System standard:

ISO 45001:2018

This certificate is valid for the following site scope:

Manufacturing of components for bodies and chassis frames by roll forming and pressing and assembly
(IAF 17)

Place and date:
Vimercate (MB), 06 August 2026

00010

For the issuing office:
DNV - Business Assurance
Via Energy Park, 14, - 20871 Vimercate (MB) - Italy

Claudia Baroncini
Management Representative

It is the management system of the whole organisation which is certified. The validity of this certificate depends on the validity of the main certificate.
Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.

ACCREDITED UNIT: DNV Business Assurance Italy S.r.l., Via Energy Park, 14 - 20871 Vimercate (MB) - Italy - TEL: +39 039 68 99 905. www.dnv.it

Certificate no.: 238682CC10-2017-AHSO-ITA-ACCREDIA
Place and date: Vimercate (MB), 06 August 2026

Appendix to Certificate

MA Automotive Deutschland GmbH - Werk Treuen

Locations included in the certification are as follows:

Site Name	Site Address	Site Scope
MA Automotive Deutschland GmbH - Werk Treuen	Treuener Hoehe, 1 - D-08233, Treuen, Germany	Manufacturing of components for bodies and chassis frames by pressing and assembly
MA Automotive Deutschland GmbH - plant Achim (MADA)	Im Finigen 2, 28832 Achim, Germany	Manufacturing of components for bodies and chassis frames by roll forming and assembly

It is the management system of the whole organisation which is certified. The validity of this certificate depends on the validity of the main certificate.
Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.